
WIRING DIAGRAM

WS 600



WS 600




Terminal assignment:

- 1, 2, 3 230 V, 50 Hz connection for mains supply
- 4, 5 Electrical pre-heating contact (option)
- 6, 7 Electrical re-heating contact (option)
- 8, 9, 10 Heating circulation pump for hydraulic re-heating (option)
- 14, 15, 16 Re-heating thermal valve / Controller for electrical re-heating (option)
- 17, 18 Outgoing air temperature sensor
- 19, 20 Outside air temperature sensor
- 21, 22 Supply air temperature sensor
- 23, 24, 25, 26, 27 Remote control interface (minimum 5 x 0.22 m², screened)

WIRING DIAGRAM

WS 600





WS 600 with DRH electrical air heater

LW 9 - air flow monitor S - sensor K1 - Contactor, electrical pre-heating, e.g. US 16 T K2 - Contactor, electrical re-heating, e.g. US 16 T DRH - electrical air heater VH - Electrical pre-heating NH - Electrical re-heating