


WIRING DIAGRAM

ATS



- ATS - temperature controller
- R1 - temperature sensor
- ATL... - ATL2.5 / ATL6 power module
- M1 - fan (three-phase AC motor)
- H - heating (floating contacts)
- A - alarm (floating contacts)
- S1 - minimum speed