


WIRING DIAGRAM

DSR 40 S



DSR... S with 1 speed




- S - control circuit
 - X - bridges for high speed
 - Y - bridges for low speed
-

WIRING DIAGRAM

DSR 40 S



DSR ... S with star-delta switch (2 speeds)



① to be supplied by the customer

S - control circuit

When using a star-delta switch, remove bridges X and Y on the terminal strip of the DSR ... S. For high speeds.
