


# WIRING DIAGRAM

## EAQ 10/1


### EAQ 10/1 combined with capacitor motor



M1 fan - (right-hand operation)

---

### EAQ 10/1 combined with capacitor motor




M1 fan - (left-hand operation)

---

# WIRING DIAGRAM

## EAQ 10/1

### EAQ 10/1 combined with shaded-pole motor



M1 - fan

---