


WIRING DIAGRAM

ERR 10/2 EC



Adjustable speed




WIRING DIAGRAM

ERR 10/2 EC



Speed adjustable via potentiometer



WIRING DIAGRAM

ERR 10/2 EC



Maximum speed

