


WIRING DIAGRAM

FS 4

FS 4



FS 4 step switch
S1 switch: On / Off
S2 switch: fast/slow
M1 fan motor