



WIRING DIAGRAM

MS 2



MS 2 with RS... external shutter, three-phase AC motor



WIRING DIAGRAM

MS 2



S control circuit
