


WIRING DIAGRAM

TR 0,4-1

TR 0.4 / 0.8 / 2.5 / 6.6



S1 switch: On / Off

M1 fan (three-phase AC motor)