


# WIRING DIAGRAM

## TR 2,5-1

TR 0,4 / 0,8 / 2,5 / 6,6



S1 switch: On / Off

M1 fan (three-phase AC motor)