


WIRING DIAGRAM

WRG20-2H

WRG 20-1H / WRG 20-2H



- S1 fan On/Off (to be supplied by the customer)
- S2 supply air shutter opening/closing, to be supplied by the customer
- S3 auxiliary heating On/Off (to be supplied by the customer)
- Z1 supply air shutter
- F1 thermal overload protection
- S4, S5 safety limit switch
- M1 fan