


WIRING DIAGRAM

DSK 50/4




- S - control circuit
 - X - bridges for high speed
 - X - bridges for low speed
-

WIRING DIAGRAM

DSK 50/4



DSK with MV 25 motor protection switch



- U1 - brown
- W2 - orange
- V1 - grey
- U2 - red
- W1 - black
- V2 - grey
- TK - white