
WIRING DIAGRAM

DZL 50/84 B



DZL...B pole-changeable (2 speeds, Dahlander circuit) with motor protection switch



PUS - Pole-changing switch