


# WIRING DIAGRAM

## DZR 50/6 B



### MV 25-1 motor protection switch




# WIRING DIAGRAM

## DZR 50/6 B



With MV 25-1 motor protection switch and TR... 5-step transformer



# WIRING DIAGRAM

## DZR 50/6 B



Pole-changeable, 2 speeds, with Dahlander circuit, with motor protection switch

