


# WIRING DIAGRAM

## ERR 20/2 EC



### Adjustable speed




# WIRING DIAGRAM

## ERR 20/2 EC



Speed adjustable via potentiometer



# WIRING DIAGRAM

## ERR 20/2 EC



### Maximum speed

