


WIRING DIAGRAM

ESR 16 EC



ESR EC sound-insulated ventilation box with potentiometer ST EC 010




Fuse and main switch provided by customer
Switching the ventilation box on and off only via 0-10 volts

WIRING DIAGRAM

ESR 16 EC



ESR EC sound-insulated ventilation box with potentiometer ST EC 3



Level 1 – 3-7 V DC

Level 2 – 5-9 V DC

Level 3 – 10 V DC

Switching the ventilation box on and off only via 0-10 volts