


WIRING DIAGRAM

ZEG EC



GNYE = Yellow / green
BU = Blue
BN = Brown
